

C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG – Director

DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

January 5, 2007

Scott Jenkins, Administrator Diamond View Assisted Living Community, LLC 3570 E Amity Rd Meridian, ID 83642

Dear Mr. Jenkins:

On December 28, 2006, a life safety code survey was conducted at Diamond View Assisted Living Community, LLC The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED 01 - ENTIRE BUILDING A. BUILDING B. WING 13R726 12/28/2006

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY F REGULATORY OR LSC IDENTIFYING INFORMAT	ULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETI DATE
	Initial Comments  The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential Assisted Living Facilities in Idaho. No cordeficiencies were cited during the standatire/life safety survey conducted on Decei 2006.  The surveyor conducting the survey was:  Taylor Barkley  Health Facility Surveyor  Facility Fire safety & Construction	or e rd mber 28,	R 000		

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE